

Upon request, operators must submit their completed programs to PHMSA or, in the case of an intrastate pipeline facility operator, the appropriate state agency.

The operator's program documentation and evaluation results must be available for periodic review by appropriate regulatory agencies.

Exits

Exits shall be marked by a readily visible sign. 1926.34(b)



Access to exits shall be marked by readily visible signs in all cases where the exit or way to reach it is not immediately visible to the occupants. 1926.34(b)

Exits must be free of all obstructions so they can be used immediately in case of fire or emergency. 1926.34(c)

Explosives and Blasting

Only authorized and qualified persons shall be permitted to handle and use explosives. 1926.900(a)



Explosives and related materials shall be stored in approved facilities required under the applicable provisions of the Bureau of Alcohol, Tobacco, and Firearms regulations contained in 27 CFR Part 55, Commerce in Explosives. 1926.904(a)

Smoking and open flames shall not be permitted within 50 feet of explosives and detonator storage magazines. 1926.904(c)

Procedures that permit safe and efficient loading shall be established before loading is started. 1926.905(a)

Eye and Face Protection

Eye and face protection shall be provided and used when machines or operations present potential eye or face injury. 1926.102(a)(1)



Eye and face protective equipment shall meet the requirements of ANSI Z87.1-1968, Practice for Occupational and Educational Eye and Face Protection. 1926.102(a)(2)

Employees involved in welding operations shall be furnished with filter lenses or plates for protection against radiant energy. Table E-2 shall be used as a guide. 1926.102(b)(1)

